



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed

Report Date: **04/09/2015**

Mine Name: Gulch Mine	Permit Number: S/023/0087	Mine Status: Active
Operator Name: Wall & Rock Inc.	Inspection Date: 04/07/2015	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 11:35-11:50	Bond Amount: \$11,700
Attendee(s):	Weather: sunny mild	Bond Escalation: 12/08/2017
Inspection Purpose: Routine inspection		Prior Inspection: 11/04/2014

Conclusions and Recommendations

The Operator has agreed not to do any mining or create any addition disturbance at the site until additional bond is posted.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds The permit fees are current. The bond is adequate and is conditioned on no mining or additional disturbance at the site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material The Operator remove most of the trash from the site. There are still two tire and some minor amounts of trash. The material are inert and do not pose a hazard.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety) The road to the site has been blocked off.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: _____

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230087-Gulch/inspections/Insp04072015.1.pdf





Two tires still remain on site. There is enough money in the bond to remove the tires if needed.



Minor amounts of trash on the site.



Loader remains on site.



Highwall on working face.